

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low	Emulated	HotKey
Input #4		1	0			0
Probe		1	0			0
Index		1	0			0
Limit Ovrd		1	0			0
EStop		1	10			0
THC On		1	0			0
THC Up		1	0			0
THC Down		1	0			0
OEM Trng #1		1	0			0
OEM Trng #2		1	0			0

Pins 10-13 and 15 are inputs. Only these 5 pin numbers may be used on this screen

Automated Setup of Inputs

確定

取消

套用(A)

Engine Configuration... Ports & Pins

Port Setup and Axis Selection | Motor Outputs | Input Signals | Output Signals | Encoder/MPG's | Spindle Setup | Mill Options

Signal	Enabled	Port #	Pin Number	Active Low
Digit Trng		1	0	
Enable1		1	16	
Enable2		1	16	
Enable3		1	16	
Enable4		1	0	
Enable5		1	0	
Enable6		1	0	
Output #1		1	0	
Output #2		1	0	
Output #3		1	0	
Output #4		1	0	

Pins 2 - 9, 1, 14, 16, and 17 are output pins. No other pin numbers should be used.

確定

取消

套用(A)