




Z - AXIS MOTOR MOVEMENT PROFILE



Velocity

Axis Selection

X Axis

Y Axis

Z Axis

A Axis

B Axis

C Axis

Spindle

Accel

SAVE AXIS SETTINGS

Steps per

Velocity

In's or mm's per min.

Acceleration

in's or mm's/sec/sec

G's

Step Pulse

1 - 5 us

Dir Pulse

0 - 5

533.333

800

100

0.0101976

1

1

Cancel

OK